919 738-6593

PRINTED: 11/19/2015 FORM APPROVED

Division of Health Service Regulation (X5) DATE SURVEY (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIER/CLIA COMPLETED IDENTIFICATION NUMBER A. BUILDING: 01 10/28/2015 B. WING HAL076005 STREET ADORESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 2925 ZOO PARKWAY CARILLON ASSISTED LIVING OF ASHEBORO ASHEBORO, NO 27204 PROVIDER'S PLAN OF CORRECTION (XB) COMPLETE SUMMARY STATEMENT OF DEFICIENCIES (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE (X4) 1D PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX DATE REGULATORY OR LISC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) C 000 C 000 Initial Comments Report of a Biennial Construction Survey by Ed Miller on October 28, 2015. Records indicate this facility was first licensed on July 17, 1996. The facility is currently Licensed for Ninety-six (96) Resident Beds, including Twenty-four (24) Special Care Beds, Based on this information, the facility is required to meet the 1996 Minimum Standards and Regulations for Adult Care Homes, applicable portions of the 2005 Licensing of Adult Care Homes of Seven or More Beds, and the 1996 North Carolina State Building Code Section 409 Group I -Institutional Occupancy. Physical plant deficiencies were noted which require a plan of correction. C 133 C 133 Bathrooms-Hand Grips SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0305 PHYSICAL ENVIRONMENT (e) The requirements for bathrooms and toilet rooms are: (6) Hand grips shall be installed at all commodes, tubs and showers used by or accessible to residents; This Rule is not met as evidenced by: Based on observation, the facility failed to ensure that commodes, tubs and showers are equipped with stable hand grips. This deficiency affects all residents who use these unstable fixtures by not providing increased safety. C133 controlled against instability/balance, and a. Grab bar in Bhall spa maneuverability at the fixtures. Findings on October 28, 2015: has been secured There was a loose hand grip (grab bar) at the Division of Health Service Regulation

LABORATORY DIRECTOR'S OR PROVIDER/SUPPLIER REPRESENTATIVE'S SIGNATURE

TITLE

(X6) DATE

12/3/2015

opporate Maintenance Director

Frientinuation about 1 of 6

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY COMPLETED IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING: 01 B. WING 10/28/2015 HAL076005 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 2925 ZOO PARKWAY CARILLON ASSISTED LIVING OF ASHEBORO ASHEBORO, NC 27204 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE (X4) ID (EACH CORRECTIVE ACTION SHOULD BE EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX CROSS-REFERENCED TO THE APPROPRIATE TAG REGULATORY OR LSC IDENTIFYING INFORMATION) TAG DEFICIENCY C 133 C 133 Continued From page 1 commode in the D Hall Spa. C 166 C 166 Housekeeping-Maintained Free of Hazards SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0306 HOUSEKEEPING AND **FURNISHINGS** (a) Adult care homes shall: (5) be maintained in an uncluttered, clean and orderly manner, free of all obstructions and hazards: La. This was completed beft present before Surveyor beft (e) This Rule shall apply to new and existing facilities. This Rule is not met as evidenced by: 1. Based on Observation, the facility failed to maintain the HVAC grilles and their associated dampers clean and free from hazards. This could affect all residents, staff and visitors if in the event of a fire the dampers do not close completely to contain the fire within the room of origin, Findings on October 28, 2015: a. The HVAC return grille with its radiation damper had an excessive accumulation of dust/lint at the employee entrance. Deficiency corrected before Construction Surveyors departed Site. C 189 Building Equipment Maintained Safe, Operating C 189 SECTION .0300 - PHYSICAL PLANT 10A NGAC 13F .0311 OTHER REQUIREMENTS (a) The building and all fire safety, electrical. mechanical, and plumbing equipment in an adult care home shall be maintained in a safe and operating condition. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e)

Division of Health Service Regulation (X1) PROVIDER/SUPPLIER/GLIA (X3) DATE SURVEY COMPLETED (X2) MULTIPLE CONSTRUCTION STATEMENT OF DEFICIENCIES IDENTIFICATION NUMBER: AND PLAN OF CORRECTION A. BUILDING: 01 B. WING 10/28/2015 HAL076005 STREET ADDRESS, CITY, STATE, ZIP CODE NAME OF PROVIDER OR SUPPLIER 2925 ZOO PARKWAY CARILLON ASSISTED LIVING OF ASHEBORO ASHEBORO, NO 27204 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (XII) COMPLETE (X4) ID PREFIX (EACH CORRECTIVE ACTION SHOULD BE CROSS-REPERENCED TO THE APPROPRIATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL DATE RESULATORY OR USC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY) C 189 C 189 Continued From page 2 which shall not apply to existing facilities. C189 This Rule is not met as evidenced by: Based on observation, the Building was not 19: Quality Sprinkler has been contacted to water new here for the has been ordered and will be completed by 12/25/15 maintained in a safe and operating condition, because some areas are not protected with fire sprinklers. This would affect all residents, staff and visitors, by not providing the protection fire sprinklers provide. Findings on October 28, 2015: In the Commercial Laundry Water Heater to) Cross Corridor Doors on Phat/ have Been Advisted AND LAtch properly with Fire Alarm (Verified by CDOM Room there was no fire sprinkler protection. Based on observation, the Building was not maintained in a safe and operating condition, because the door(s) protecting the opening in the smoke barrier did not close completely and latch to restrict amoke. This could affect all residents. 39) All penetrations in Ahall Electrical 1200m have been Fire Caulked b) All penetrations in Main Electrical Room have been staff and visitors by not containing the smake to the fire compartment of origin. Findings on October 28, 2015: The front leaf, of the double-egress cross-corridor doors on A Hall, did not latch when the fire alarm system released the doors. Based on observations, the Building was not maintained in a safe and operating condition. Firecaulteed because of breaches through the fire-resistance-rated construction invalidates its integrity. This could affect all residents, staff and visitors if smoke/fire is not contained in Room or compartment of origin. Findings on October 28, 2015: There were gaps/holes behind conduit that penetrate through the fire-resistance-rated ceiling assembly in the A Hall Electrical Room, There were gaps around 2 unsealed cables that penetrate through the fire-resistance-rated ceiling assembly inthe Main Electrical Room,

Division of Health Service Regulation (X3) DATE SURVEY COMPLETED (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION IDENTIFICATION NUMBER AND PLAN OF CORRECTION A. BUILDING: 01 B. WING HAL076005 10/28/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2925 ZOO PARKWAY CARILLON ASSISTED LIVING OF ASHEBORO ASHEBORO, NC 27204 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X8) COMPLETE (X4) ID (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX PREFIX DATE REGULATORY OR LSC IDENTIFYING INFORMATION) TAG TAG DEFICIENCY C 189 C 189 Continued From page 3 CIES C) Proctention in Main Diving Room has been Fire coulked In the Dining Room there was a penetration through the fire-resistance-rated ceiling assembly by an open ended sleeve. d) Hole in Ec. Ing at Commercial Laundry Room has been Repaired and Sealed The ceiling in the Commercial Laundry Water Heater Room had a two inch diameter hole through the fire-resistance-rated ceiling assembly. Based on observation, the Building was not 49) Éscutchem has been nostellue at centrus b) Escutthen in Riser Room maintained in a safe and operating condition, because the fire sprinkler escutcheon plates were impaired, exposing openings through the fire-resistance-rated construction. This could affect all residents, staff and visitors if smoke/fire has been installed is not contained in the Room or compartment of O) Hole at Excutched in Private Diving Room has been Saul Findings on October 28, 2015: The fire aprinkler escutcheon plate had dropped down from the ceiling in the Room d) AT Esculcturan has been behind the commercial dryer, The fire sprinkler escutcheon plate had b. replaced dropped down from the ceiling in the Riser Room, estshall Quet Quan Closest The fire sprinkler escutcheon plate did not cover the complete hole through the cailing in the Escutifican has been Replaced Private Dinning Room, The fire sprinkler escutcheon plate was missing in Bedroom A-7. The fire sprinkler escutcheon plate was missing in D Hall Quit Room Closet. Say Dhall Housekeeping Closet has been realigned Ands adjusted to close properly (VEV. F. a.D by CDOM Based on observation, the Building was not maintained in a safe and operating condition, because the corridor doors did not resist the passage of smoke due to door leafs not fitting into their fames with acceptable gaps under normal operating conditions. This could affect all residents, staff and visitors if the doors did not contain smoke/fire in the room of origin, Findings on October 28, 2015: a. D Hall Housekeeping Closet corridor door did

69YW21

Division of Health Service Regulation (X1) PROVIDER/SUPPLIER/CLIA STATEMENT OF DEFICIENCIES (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING: 01 B. WING HAL076005 10/28/2015 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2925 ZOO PARKWAY CARILLON ASSISTED LIVING OF ASHEBORO ASHEBORO, NC 27204 SUMMARY STATEMENT OF DEFICIENCIES PROVIDER'S PLAN OF CORRECTION (X5) COMPLETE DATE PREFIX (EACH DEFICIENCY MUST BE PRECEDED BY FULL EACH CORRECTIVE ACTION SHOULD BE PREFIX REGULATORY OR LSC IDENTIFYING INFORMATION) GROSS-REFERENCED TO THE APPROPRIATE TAG TAG DEFICIENCY) ረነፀዋ C 189 Continued From page 4 C 189 not fit into its doorframe without exerting more that the normal closing force to get the door to B) D4 ENTINGE Door has been Adjusted to close and Latch property (ventured by CD.M) latch. Bedroom D-4 corridor door did not fit into its. doorframe without exerting more that the normal closing force to get the door to latch. Based on Observation, the Building was not 69) Wesler has been Removed and clisiossecthatitis wat allowed Anywhere in Facility maintained in a safe and operating condition. because some corridor doors were held open by devices that do not release with a push or pull of the door, preventing the doors from being closed and latched rapidly. This could affect all residents, staff and visitors by not containing smoke and fire in the room of origin. Findings on October 28, 2015; a. The corridor door to the Bedroom A-12 had a wedge holding the door open. C 199 Exhaust Ventilation C 199 SECTION .0300 - PHYSICAL PLANT 10A NCAC 13F .0311 OTHER REQUIREMENTS (g) The spaces listed in this Paragraph shall be provided with exhaust ventilation at the rate of two cubic feet per minute per square foot. This requirement does not apply to facilities licensed before April 1, 1984, with natural ventilation in these specified spaces: soiled linen storage; soil utility room; (3) bathrooms and toilet rooms; (4) housekeeping closets; and (5) laundry area. (k) This Rule shall apply to new and existing facilities with the exception of Paragraph (e) which shall not apply to existing facilities.

Division of Health Service Regulation STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA AND PLAN OF CORRECTION IDENTIFICATION NUMBER:		(X2) MULTIPLE CONSTRUCTION A BUILDING: 01		(X3) DATE SURVEY COMPLETED	
- mar Parity		HAL076005	it. WING		10/28/2015
NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY, STATE, ZIP CODE 2925 ZOO PARKWAY ASHEBORO, NC 27204					
(X4) ID PRÉFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC (DENTIFYING INFORMATION)		ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTI (EACH CORRECTIVE ACTION SHOUL CROSS-REFERENCED TO THE APPRO DEFICIENCY)	D BE COMPLETE
C 199	Based on Observated to maintain the working order. This and visitors by sub Findings on Octobra. The exhaust wadequate air in Baths. The exhaust wadequate air in A Hor. The exhaust wadequate air in Cod. The exhaust wadequate air in D Hor.	et as evidenced by: ervation and testing the facility ne ventilation system in proper s could affect all residents, staff jecting them to odors. er 28, 2015: entilation was not moving throom in Bedroom A-7, entilation was not moving lat! Housekeeping, entilation was not moving mmercial Laundry, entilation was not moving	C 199	CAG Ia) A7 Both Exhaust has repaired b) Ahall Housekeeping: Fan has been repaired c) Exhaust Fan in Commit Languagh has been in Dhall About To. lot has been e) Exhaust Fan in Dhall keeping has been repaired A11 Exhaust repaired been made 12/3	ercial repaired Nepaired Noose-

68YW21